

Ensure master linkage arm
is perfectly vertical when the
throttle plates are fully closed

